

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

### -- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

### -- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



VOLUME XVIII . NUMBER 1 . SEPTEMBER/OCTOBER 1999



# STATE TOROUGH TOR THE POBLICATION FOR MEMBERS OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE TENDER OF THE 1937-1938 BOTCK ELOB - VOLUME AVIT ADMISER THE 1937-1938 BOTCK ELOB - VOLUME AVIT

"Can I be of any help?"

Well, we ended our 1998-1999 publishing year August 31 with a total of **630** paying mem-

bers, an all time high. Included with the last issue was the new Club Roster. It includes all members up to August 8, 1999. A few new members joined after that date and are not included. Also, if you spot any errors in your record, please let me know so that I can correct them for the next Roster. Thanks.

In 1999 the Torque Tube won two awards, one from the Buick Club of America (BCA) and one from Old Cars Weekly. We couldn't have done it without membership support and encouragement. Keep sending in tech tips, interesting photos and 37 &

38 Buick articles. Thanks for your continued support.

The Bear, a Buick powered dragster was featured in the January, 1954 "Car Craft" magazine. It had two things about it that caused crowds to gather. One was the way it looked and the other

BUICK POWERED DRAGSTER


how fast it went. The first time out, the driver and builder turned 130.6 mph (209 km/hr) Here are some interesting quotes from this article:

"The builder picked a straight eight engine block around which to build his hot rod for two rea-

sons. (1) He claims there is more efficiency per pound in a straight eight than any other engine, and (2) because of the efficiency of the overhead valve system as compared to the L-head type used in most V-8's."

"Starting with a 1936 Century block and by boring it an 1/8 inch he brought it up to 340 cubic inches. The stroke and flywheel are stock. Also stock is the 1938 Buick Century transmission that "The Bear's" owner has built into his speedy drag machine. The pistons are Egge and are connected to the crank shaft by '49 Buick stock connecting rods."

Six reworked Stromberg 97 carburetors dump fuel into a box manifold. Eight chrome plated



headers direct exhaust gas out. Thanks to *Greg Korzeniowski* (#1405) in Canada for sharing this article.


American movies have produced some of the most memorable, as well as some of the most forgettable films in history. One cinema format was the weekly "serial" (installments) at theaters, to keep the customers coming back every week.



Over 200 "cliff hangers" were made in ten to fif- chrome hubcap to the sidemounted spare. No-

teen episodes that left the audience sitting on the edge of their seats wondering if the heroine would survive the fact that she was tied up in a boat going over a waterfall or the hero being locked in a room where the walls were closing in to crush him into hero juice.

One of these was made by Republic Pictures and released in 1951. These three photos show a serial called "Government Agents vs. Phantom Legion." Chapter 7 features a chase scene between a 1951 Ford sedan (the bad guys) and a 1938 Buick Special Convertible Coupe (good guys - photo A). In some close-up scenes you can see the car had an ivory colored steering wheel as used on '38 Specials. And for some reason they attached a







tice there is not a BUICK 8 bumper badge. (Some '38 Buicks, usually Specials, did not have this badge or a hole in the bumper for one as in the case of the 38-46C ad at the top of page 3. Thanks to Anthony Wright (#1192) in NYC for sharing this ad).

Photo B, on this page, shows another interesting feature. The car has only one sidemount. In photo C, showing a wild chase scene, the 38-46C suddenly becomes a 37-46C with the correct sidemount faceplate with the BUICK emblem and an aftermarket center front bumper guard. I wonder how many people caught this continuity mistake when this serial came out?

At the end of the chapter, the 37-46C gets caught in a wall of

# **TORQUE TUBE**

#### You can now find your '37-'38 Buick Club on the World Wide Web: http://www.classicar.com/clubs/buick/buick.htm

The TORQUE TUBE is published every two months for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Editor: Harry Logan, #651 Printer Liaison: Bill Olson, #427

Art Director: Dug Waggoner, #10 Printer: Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE.

n

flames set by the bad guys and explodes. You'll have to see Chapter 8 to find out if the good guy in the convertible was really killed! (ED: He survived because he jumped out just before the explosion, but it looks like the 37-46C was sacrificed). Thanks to Von Hardesty (#964) in Arlington, VA for sharing this very interesting video.

They push the button-BÚICK DOES THE REST!

like a lot of money for a In 1937, Buick offered chrome wheel discs. strange looking car. I had just spent \$1,300 for

(photo A) They were listed in the Accessory Price List. They were not listed in the 1938 Accessory Price List, so presumably they were dropped because they did not sell well.

my unrestored 38-46C." Does any member have more information on the custom '38 Limited?

les home looking for parts

around 1970. In the mid-

70's Wayne Yonce (#1034-

Fallbrook, CA), took these

nighttime photos on page

4 that show the same cus-

tom bodied Limited. The

car has a 1933 Buick trunk

rack. It was parked in Bell-

flower, CA (LA area) and

was for sale for \$3,000.

Wayne says "That seemed

Bob and Doreen Ward (#905) own a 1937 McLaughlin-Buick Limited Model 90L with chrome wheel discs and Canadian-Buick hubcaps. (see B & C below) This is the only car I've ever seen with wheel discs.

The next photo, on page 4, shows Wayne and Ann Yonce with their beautifully restored Corot beige 38-46C.



Now meet one of our newest Club members, Janet Ricketts (#1446) in Tarpon Springs, FL. She is the President of the Antique Automobile Club of

America (AACA). She and her husband John





This Corot beige cutaway '38 Buick was shown at car shows. I guess the railing around the car was to prevent people from touching it.

were given a gift subscription to the Torque Tube by their friend, and ours, Wayne Yonce.

In the Sept/Oct, 1998 issue of the Torque Tube, page 1 displayed a photo of a 1938 custom bodied Limited that showed up at Greg Field's Los Ange-


Janet told her husband that this could be an expensive year since a 1938 Buick Special Sports Coupe Model 465 with dual sidemounts caught her eye in Orlando, FL.


writes: She "Like most people, buying a car is an emotional experience. I saw this little Buick and I made the fatal mistake of telling the owner that thought it was a real nice car and he remarked...'It's for sale.'

The next thing I knew, I was test driving the car and then bought it. The main reason was because I thought it was a good size for me to drive. I plan to get more involved in local tours." Thanks to the Antique Automobile, the official publication of the AACA.

California member Walt Brugger (#1444) has

followed up his book "The 1935 Buick Story" with a similar book on the 1940 Buicks. It contains 83 1940 Buick ads. It also covers such major events as the introduction of the "Y Job," the Estate Wagon, the Town Car, the 1940-1/2 "C" body Buick convertibles, and the telegram announcing to the world the assembly of the record breaking 250,117 1940 Buick, the





Indianapolis 500. "Gone With The Wind", the first freeways etc. The book costs \$25 including 1st class postage. If you're interested, you can order directly from the author:

Walt Bruegger (#14444)1289 Magnolia St.#1 San Carlos, CA 94070

This 1939 Century Sport Coupe Model 665 belongs to Anthony Wright (#1192) in New York City. Note the period dress of the men. Anthony used his car to help a photographer friend

shoot the cover scene for a Compact Disc (CD). The location was on West 15th street in Manhat-

tan, (NY City).

The music group is called the Blues Jumpers. They are part of the Swing Scene revival.

Here's a photo of Count Basie's CD from the same period as our cars. Anthony has included an amusing excerpt from The Count's own autobiography. "Good Morning Blues."

It was in the summer of 1936 when Count



Factory Driveaway plan, the 1940 radio, the 28th Basie was getting ready to take his band on the

road for the first time. It seems the Count came into a little money, so he decided to put some of it down on a BUICK. But the president of the Musicians Union heard about it and

thought that he had used band money. But this dispute was soon resolved.

The Count loaned the car to one of his musicians who drove it to Los Angeles and back. Then he and a friend drove it to Chicago and back to NYC.

The Count's new Buick could be either a '36 or '37. Does any member have Buick magazines from these years. If so, please look for the section on photos of Buick owners. I'm sure if a famous person like Count Basie bought a new Buick, he'd be in the magazine. Let me know what you find out. Thanks.

The 1937-1938

Buick Club Eastern

Meet and Tour will be held
next year at the St. James Hotel in picturesque Red Wing,
Minnesota. Red Wing is located on the Mississippi
River. Minneapolis is the
closest big city.

The Meet will be held from Tuesday June 6, through Friday June 9, 2000. We'll take some great tours through the scenic Hiawatha and St. Croix River Valleys. *Dave Wettersten* (#887) will be our Tour Director. More information in the next issue.

1937 and 1938 Buicks carried hard working



waning days of the great Depression, World War II and into the industrial boom which followed the end of worldwide and debilitating hostilities.

Now you can buy

people through the

1/43rd scale model of one of these Buicks, a 1938 Special Sedan with plain fenders and '38 New Jer-

sey license plates. The cars come in either Titian (dark) maroon or Botticelli (medium) blue. Actually, these models (top of page 6) could also represent Centurys as the look is the same.

The only place it says Special is on a manufacturer's tag on the bottom of the car.

The models are made in France in small batches. They are hand assembled and painted. Customers should inquire about availability before ordering. The cost of these models is approximately \$130. They accept Visa or MasterCards. If you're interested, contact:

Raymond Paszkiewicz Jr. PO Box 156 Clarksburg, NJ 08510 Tel: (732) 446-9381

These last photos show a 1938 Century Convertible Coupe belonging to *Gary Glazier* (#1005) in La Cresenta, CA. His car has Trippe driving lights.


But Gary had admired Guide Super-Ray lamps for a long time. Then the Super-Ray article in the May/June 1998 *Torque Tube* 

inspired him to find a pair. Gary likes them much better than the Trippe lights that were on his car.

Sorry for the delay in getting the last issue out. Producing the *Torque Tube* is a three stage process. First, I send the text and photos to our Art Director *Dug Waggoner* (#10). Then he scans











in the photos and combines those images along with my text in the computer. He designs the page into the nice format we've come to expect to get it ready for the printer. Finally, it's mailed to the Conrad's Printing in Ohio who prints, binds, trims, stuffs it into the large envelope, applies the mailing labels and stamps and takes it to the post office. Club friend and former editor *Bill Olson* takes care of getting the mailing labels to the printer and buying the stamps as well as mailing the copies to our overseas Club members.

So if any one of these stages is late, so is the *Torque Tube*. And that's what happened. Issue XVII-#6 together with the Club Roster, as well as the renewal envelope, was in effect two issues at one time. We were a little delayed on this end and the printer was swamped with business which delayed it even more. Thanks for your continued patience and understanding.

Hally

# Cover Cars

The front and back covers show **Rene Delhomme's** (#676) 1938 Flxible Hearse on a Buick Special chassis. See the story below.

# 1938 Buick Flearse By Rene Delhomme Sr. (#676)-Layfette, Louisana



In 1981, a friend told me he saw an old hearse behind a gasoline station in New Orleans. So we

went to look at it. It was in terrible shape, but I thought that maybe I could restore it. So we paid the owner \$300 and towed it 170 miles to my home.

Our family has been in the funeral business since 1921, so we parked it at one of our funeral homes. It still had a tag stating it was a 1938 Buick Flexible hearse (No. 2975-49-9) on a Special chassis, frame no. 13384163, motor number

43568756. In researching, it turns out it was a Sterling Classic "A" funeral car with carved-type panels and a factory drive-away price of \$2,995.

Now, eighteen years later, having given up

on the project two times, and my wife and fellow employees asking what I was going to do

with it, it's now finished.

After struggling with many different people and partial repairs, I entrusted it to a master mechanic, electrician, carpenter, body-man and painter all rolled into one. In his single car workshop, over a five year period, he completed what I consider a miracle. His name is Larry Sikes, and he owns the Nostalgia Auto Works in Church Point, LA.

I guess my pleasure and hobby with this was trying to find the parts so that it all could be put together. My thanks go to Hemmings, The 37/38 Buick Club, Buick Club of America, The Profes-





sional Car Society, and all my friends and family.

In the search for parts, I would visit a friend who owned a 1938 Roadmaster sedan to see what I was missing or where I had taken a certain part off of. Finally after years of doing this, he got tired of me coming over I guess, so he sold me his car. So now I have the family car and the hearse.

In fixing the interior, we used pictures from the book "Flexible Professional Vehicles: The Complete Story" by Thomas McPherson. We were able to use the pictures by bringing them to a graphics studio that approximated the size and dimensions of the appliqués on the inside and then I brought the designs to a woodwork shop and they created them perfectly.

A friend and I put the woodwork into the rear of the hearse. We still had the rollers and stops, so we had them rechromed, put dark blue leather on the inside, making it look better than when it was new. And now it's finished! We have used it for one funeral, that of a Cajun musician. (ED: If any member is interested in restoring another 1938 Special Hearse, **Dave Tacheny** (#997) in Minnesota has one for sale. Phone (612) 427-3460).





# MY D-DAY!

The same of the sa


#### D-AS IN DISASTER

Secretary of the second second

By Mal Oneill (#1425)-England



This was my 1937 McLaughlin-Buick Special 4-Door Trunk Back Sedan as it looked two months ago. It was fitted with a division window behind the driver. It had two radios, one in the front for the chauffeur and one at the rear. The first owner was the Manager of the Radiant Sweet & Candy Company in Doncaster, England In July, I took it to a big American Car Show called the Americana. But I'm sorry to report that as of August 20, my car no longer looks like this.



This is how it looks now.



American style: The 1939 Buick in its full glory

## Fire destroys years of work restoring car

A MECHANIC has been left heartbroken after the classic

car be had lovingly restored was devastated by fire.

Malcolm O'Neill was rushed to hospital suffering an angina attack after his 1939 Buick was destroyed in a mys-

angina attack after his 1939 Buick was destroyed in a mys-tery garage blaze.

Mr O'Neill bought the car 13 years ago and spent his spare time and money returning the rare American model to its former glory. He said: "It was my dream car - it be-came like one of the family - and now it is just ashes."

The car, which had two radios and an inside partition, was regularly used for weddings and displayed at rallies.

The have consed through the greater in the carbon have

The blaze ripped through the garage in the early hours of yesterday, reducing the car to a burnt-out shell. Mr O'Neill, of Williams Street, Bishop Auckland, said:

"I wanted to try and save the car but my wife held me back "I just sat on the steps crying until the fire brigade arrived. I had an angine attack because of the shock."

After a short stay in hospital he was allowed home and


After a snort stay in nospital he was allowed nome and is now contemplating life without his prized motor. He said "I can't see it on a scrap heap. I am going to do some work to try to save as much of it as I can. Initial investigations by the fire brigade and policy rerealed the blaze started inside the car, which had been

locked in the garage at the time of the incident.



Dream up in smoke: Malcolm O'Neill looks over the gutted remains of his pride and joy





So now I'm looking for a 1938 Buick Special Model 41 Trunk Back Sedan with twin side mounts to take it's place. Must be restored or close to it.



If you know of a car like this, contact me at:

Mal Oneill (#1425)

Auckland Park Bishop Auckland

Durham Co.

ENGLAND DL14 8RI

Phone: 01388 602800

PS I hope a club member will ring me!

# 1999 BCA NATIONAL MEET

Columbus, Ohio
By Cecil Don (#637)-Yuba City, CA



Our 1937-1938 Buick Club was well represented at the 1999 BCA Nationals.

Eight members won prizes , 5-1937's and 3-1938's.

Here is a sampling of some of the winner's.

This is **Karl and Barbara Bosk's** (#1154-Michigan) recently restored green 1937 Special Convertible Coupe Model 46C.


It won the GOLD New Senior Award.



Another GOLD New Senior Award went to *Jack Frank* (#739-Pennsylvania) for his green1937 Special Convertible Sedan Model 40C.



Vince and Betty Pullara (#1433-Maryland) won a Silver Award for their black 1937 Special Convertible Coupe Model 46C.



This black 1938 Century 2-Door Trunk Back Sedan Model 68 belongs to *Carl and Joyce Lohstroh* (#1098-Georgia). It won a Silver Award. It's a rare car, there are only two in the Club.



There were also some 37/38's for sale. Here are a couple of examples. This is David Bylsma's (#117) in Maryland) maroon '38 Century Convertible Sedan Model 60C. Phone (410) 551-7236...... \$28,000. This blue 1937 Roadmaster Sedan Model 81 was offered by Richard Gumm in Ohio. Phone (740) 374-8169....... \$8,500.



Thanks to all our members who helped make this

possible by submitting articles, photos, ads etc. It wouldn't have happened without your help! Thank you.

# MY DAD'S LOUGHEN


By John Stewart-San Jose, CA

In 1940 my dad bought a maroon 1937 Buick Roadmaster in Hanford, California That's my sister and me on the right with my dad's maroon Roadmaster in the background.

It took our family of four to Kansas in 1942 for a reunion. I was


6 years old. On the way home, I thought I would iron the blanket hanging over the back seat. I used one of the two cigar lighters which were in the armrests on either side. Mom smelled wool burning. I didn't know why she made such a fuss.

The package shelf behind the rear seat made a good place for a nap. A "privacy curtain" rolled up to cover the rear window. It hooked on a chrome button. When mom drove, the front seat was moved forward while the back of the seat





the gap. I could lay up there and fall asleep. The crank opened "wind wings" in the front and back providing ventilation in the August heat as we crossed the dry New Mexico desert. During World War II, tires were scarce. We had one



stayed stationary,

empty wheel well on the right side. I must have been 7 years old when, after much begging, my dad let me ride inside that wheel well. I held on to the

big bolt, the parking light was my "rocket ship." We drove through town and 10 miles out into the country with the wind blowing in my face.


I remember the folddown foot rest tucked under the back of the front seat. And the robe cord draping against the stationary part of the back seat. We drove the winding road to Sequoia National Park many times in summer and winter.

When I was 9 years old, returning from one of these trips, my sister and I were in the back seat. I stood in front of her and would fall toward her, she would push me away, and I would fall toward her again. My right elbow hit the door handle and the door flew open. I went out at 60 mph. The corner of the door cut my lip as I went under it. I bounced and skidded to a stop, opened my eyes to see my dad stop and open his door. I got up and ran to him. I came home from the hospital on the day President Roosevelt died.

Cars nowadays don't have room enough for a kid to stand in front of the back seat, and they don't allow the inside door handle to override the door lock button. About my 10th birthday the car was painted a rich dark green, almost black. And the seats were re-upholstered green plastic on top and cloth below.

We made a second trip to Kansas in 1952 when I was 16. I got to drive part of the way. The water pump rusted through. A mechanic made a patch which held until we got to Turon, Kansas and could buy a used water pump. Coming down a grade toward Las Vegas, the transmission howled. The noise quit on the level and we never got it fixed.

After a dance in 1954, the car backfired, coughed, and spit. I tried racing with my girl-friend but the car embarrassed me. A week later some boys asked if I had seen guys tampering



boards as the antenna.

Teen age years are hard on a car. I chased a 1949 Buick Super and a 1947 Cadillac one night and caught up to both of them. The right front wheel was bouncing but seemed to settle down over 80 mph. Two days later, in high school auto shop, I discovered the top bolt in the right front king pin connection to the A-arm was backed out about half way. What a lesson!

But I destroyed the rear end trying to get "second gear rubber" a few months later. The right front fender folded in the aluminum front fender of a French Simca from my lack of road smarts.

My friend and I unbolted the head and tried to lift it off, then we found that the dual carburetor manifold that we had spotted at a junk yard was too short to fit because it was for a Special. So we bolted everything back in place.

My dad died at age 65 in 1954 during my senior year in high school. The car was sold to a nice Mexican family in 1956. It had 130,000 miles and 16 years of family history in it. I went from Kindergarten through my 2nd year of College with that car. It was hard to see it go.

## 1937-1938 BUICK ITEMS SEEN ON THE INTERNET

Here is a sampling of some 37/38 Buick auction items for sale on the Internet through *eBay*. You can visit eBay, the world's largest Personal Trading Community at *http://www.ebay.com*. This is to give you an idea of the kinds of Buick items available. Most of these are probably sold by now.

1938 Buick Stationery. This is a really unusual piece. It is a sample stationary package that was sent to the Buick dealers for 1938. It contains sample business cards, envelopes (3 different sizes), letterhead, invoices, a sample blank check and other sample goodies. This is a real nice conversation piece if you are a 1938 Buick fan or just a collector of Buick memorabilia.

1938 Buick rear doors off of 40 series sedan. These were taken off during the 1930s-40s.. I got them about 30 years ago from a large salvage yard located in the state of Maine. The doors have most of the hardware and chrome on them.. Good solid doors. Will not ship but will hold them until arrangement can be made for pick up.

This is the bumper-mounted step plate to allow access to the rumble-seat of your 1933, 1934, 1935 (and I think it even was used up to 1938) Buick Rumble-Seat Coupe or Convertible.

(I don't have the fendermounted one) The step plate itself is an excellent reproduction, but the mounting base (in primer) and screw are original. I bought it over 25 years ago and it has been in dry storage ever since.

Of all my old

Buick Hubcaps, this one I like the best. Maybe it's because I once had a 1938 Model 87... the rarest of the rare. Look it up in your "70 Years of Buick" book and you'll see what I mean. This one fits all 1938 model Buicks and is the absolute best you will find. I had it on my car once for a photograph. All original; no reproduction. I've had it for 30 years. IF YOU NEED A HUBCAP FOR YOUR 38 BUICK, YOU WON'T FIND

A BETTER ONE!

1938 BUICK sales brochure 38 pg. This original brochure covers Limited Series 90, Roadmaster Series 80, Century Series 60, and Special Series 40 lines. Full color artwork of each model, 21 total!!! The artwork is superior with classy chrome finished borders. Each model has original sales price neatly written in, via fountain pen, underneath. Just think a Series 60 four passenger convertible for just \$1,202. Brochure also contains excellent artwork of the Dynaflash 8 engine, interiors, chassis, dash, mechanical components, drivetrain, and a full page of factory specs. Excellent condition, flat storage since the thirties. Spine has some black ink worn off but is not split and is still strong. Any questions please e-mail.

NO RESERVE!

This is a near mint 1938 Buick Owners manual with envelope, battery warranty card, blank owner ID card, service policy, upholstery care booklet, electric clock instructions and electric clock installation instructions. A very nice collectible. Buyer pays actual shipping.

And there were two cars for sale. One is this

1937 Roadmaster Sedan with a reserve of \$8,600. Interestingly enough, this is the same car For Sale at the 1999 BCA Meet in Columbus. See page 14 for a better photo.

The other is a 1938 Buick Businessman 2-Door Coupe. Original

straight 8, 3 speed on the floor. Modifications-Changed to 12 volt system. Excellent running condition. No rust, black cherry paint job. All metal, no dents, very little wear on the running boards. Interior in excellent condition. Theft alarm included. It had a reserve of \$10,000.

Thanks to **Von Hardesty** (#964) in Arlington, VA and **Charles Jekofsky** (#524) in Washington, DC for sending in these auction items.






## Technical INSTALLING **SEAT BELTS**


By Harry Logan (#651)-Los Altos, CA

Installing seat belts is a good safety investment. Most car shows will not deduct any points for cars with safety belts. I know I am so used to wearing seat belts in my modern cars that I feel naked without one in my old Buicks.





One of the decisions you'll need to make is what type of mounting to use. The two main choices are hook and eye-bolt (A) and bolted mounting (B). The hook belts have the advantage that you can easily remove them at a show to make the car look more original.



You can also use retractable belts (C). Most seat belt vendors do not sell this type of belt. These were removed from a car in a wrecking yard.





They have the advantage that half the belt is out of the way when not in use (D).

To mount the belt anchors (E), most people drill a hole through the floor pan behind the front seat. My belt anchors are 16 inches (41 cm) apart. Before you drill, check underneath the car to make sure you won't hit something (like the muffler). You might want to drill a small 1/16" test hole first, then push a wire through it to make sure the hole is where you want it. If it isn't, the 1/16" hole is easily hidden.



Some mount the bolts through the "X" portion of the frame for stronger support (F). This requires some careful measurement so that the bolt holes go through both the floor pan and frame.






It also means the anchors inside the car will be offset from each other in order to go through the slanting "X" portion of the frame (6).

Another consideration is that mounting the belts to the frame might cause a serious problem if

the body should break loose from the frame in a severe accident.

All this being said, most people mount the belts to the floor pan. I have even seen one 38 Buick with three point seat belts instead of just the two point lap belts. But this requires drilling a hole through the body center post.



And you convertible coupe owner's, don't forget the rumble seat. Children often ride in them and can be easily thrown out. This convertible owner mounted a steel plate (H) under the wooden rumble seat bottom to anchor the belts.

## DON'T THROW **AWAY THAT TEMPERATURE** GAUGE



By Saul Hoffman (#666)-Ben Lomond, CA

If you're replacing your temperature or other through the rivets and the face plates separated

look as good as the original, just exchange the dial's.

The water temperature gauge on my 1938 Special Coupe never worked since the day I bought the car. So 1 purchased another gauge (A) and tested it with a pan of boiling water. It read 212°F (100°C).


It wasn't until after removing the broken gauge from my dash that I noticed

than on my original. The replacement dial,

which wasn't in great condition, had small colored circles and was from a '37 Buick (B). '38 dials have vertical lines indicating temperature. Since my original dial was in mint condition, I decided to see if I could remove and mount it in place of the replacement.

The dial is secured to the operating part of the gauge by two small hardly noticeable. So now I have a working

aluminum rivets (C). Using a 1/16" drill. I made a hole





so that the drill bit wouldn't scratch the face plate if it slipped off the rivet (which it did). Knowing that I did not have a rivet or screw with nut that small, I scoured the local hardware and auto parts stores without success. Coming home I took my eyeglasses off and while scratching my head, I saw that they were held together with small screws

that the dial on the replacement was different and nuts. A quick trip to the optometrist was successful, and I picked up two small fully threaded screws and nuts.

> They fit the holes in the dial perfectly. I picked up some extra nuts since they are very tiny, and easily lost.

It was a bit tricky getting the nuts on and I doubled them up on each screw so as to lock them. then cut-off the excess screw length. The screw heads on the face plate are water temperature gauge with a nice looking dial.










By Harry Logan (#651)-Los Altos, CA

## MASTER DISCONNECT SWITCH




This is a typical master disconnect switch (A). They cost around \$30. The difference between this high current switch and a low current one is the size of the contacts which are concealed inside the cover.

A high current switch is needed because 200 or more amps flow when you start your car. The switch terminals where the wiring attaches

are large in diameter so that thick, high current cables can be connected. The whole idea is to use a switch that can completely disconnect the battery from the electrical system. There are two good reasons to do this, safety and security.

Even though your wiring harness is new and correctly installed, cases of current leakage re-



sulting in a dead battery can occur. Some members have had their clocks converted to quartz. These will draw a small amount of current if the battery is left connected. And over time it

will run down the battery. The same thing will happen if you accidentally forget to turn off the under-dash switch that controls the instrument lights. And if a wrench or other metal object should touch the positive battery terminal or cable and ground, a short-circuit fire

could result! But a master switch at the battery makes this impossible. And it also helps prevent someone from stealing your car.

There are several places you might consider mounting a switch. This one is mounted through the fender side-panel with the knob under the right front fender (B). It makes the cable runs in the engine compartment short,

under the fender and around the tire to turn it on. Very awkward!

Some owners mount the switch on the engine side of the firewall with the knob in passenger compartment. The knob is then close the to heater. And if only you know where it is, you may succeed in prevent-

ing your car being stolen.

The switch can also be mounted in the floor pan, near or under the passenger's seat. This is close to the cable coming from a 1937 Buick's under-seat battery. The disadvantage is that the

switch is exposed to water and dirt thrown onto the switch, causing possible leakage current or corrosion. It's best to keep the switch dry if pos-

> Here's another type of disconnect switch It attaches right at the battery terminal (C). Loosening the

round knob disconnects the battery. You can also unscrew and put the knob in your pocket for maximum security (D)

Either the

hot or ground side of the battery can be switched. Most people choose to switch the negative terminal as it is the safest way.


I do not use a disconnect switch on my 1938 Buick because the battery is now under the hood and easily accessible. I tighten the negative battery connector so that it is tight, but loose enough so I can remove it by hand. I remove the cable at night and twist it on to the

terminal when I want to drive. It's a very simple and easy operation.

I've been doing this for years. It also has the advantage that it always looks original and there are no switches to bother with.

Disconnecting the battery quickly has also saved me from a possible disaster


when I suddenly developed a short circuit in my old wiring harness while getting gas. Smoke started coming from under the dashboard. I jumped out of the car and quickly removed the negative battery terminal. All's well that ends well!






# CONVERTIBLE COUPE FRONT FENDER BRACES

By Harry Logan (#651)-Los Altos, CA





### CORRECTION TO 1999 ROSTER

Please add this, Member Cars Year, Model & Series listing, on page 32, that was left out of your new 1999 Club Roster.

#### 1937-81

Brakke, Landy
Breen, John
Campbell, Douglas
Cohen, Allan
Cohen, Lewis
Delgado, Richard
Forster, John
Greer, W. T.
Huffman, John
Kaulhold, Rod
McGray, Larry
Moore Sr., James
Pardo, Jose
Preslan, Clint
Schindler, Ray

# CORRECTION ON DATA PLATES

This is the correct photo that should have appeared at the bottom of page 14 in the last issue. The article was about "Interesting 37/38 Data Plates." The text (repeated below) was correct.

"This data plate is on **Bob Lawrence**'s (#653) 1937 Special 4-door sedan Model 41. It is the only data plate I have ever seen where the date is filled in. It is stamped 11-24-36, indicating an early production '37 Buick. The paint was #501 Chancellor (dark) blue with #301 upholstery (tan mohair fabric)."



Randy Hosler (#1443) 6585 Dixie Highway Clarkston, MI 48346 38-66S

Walter Bruegger (#1444) 1289 Magnolia Ave. #1 San Carlos, CA 94070

Arnold Isaacs, Jr. (#1445) 20010 Colony Point Lane Cornelius, NC 28031

Janet Ricketts (#1446) 2941 Magnolia Trace Tarpon Springs, FL 34689 38-46S

David Anderson (1447) 401 Wayman Drive Greer, SC 29651 38-61

# New Members

John Hollenback (#1448) 2445 Terwood Rd. Huntingdon Valley, PA 19006 38-41

Ty Steward (#1449) 3458 Sagehen Way Sacramento, CA 95834

John Crequer (#1450) 23 Helensburgh Road Dunedin, New Zealand

Jim Lo Cicero (#1451) 60 Orland Square Dr. Orland Park, IL 60462

James Wright (#1452) 137 Droms Rd Scotia, NY 12302 38-46S James Woolsey (#1453) 2052 Cima Ct. Carlsbad, CA 92009

E. Allan Bosshard (#1454) 25306 29th Ave. S. Kent, WA 98032 38-46

Karl Heinz Pydde (#1455) 267 Mt. Morton Rd. Belgrave Hieghts 3160 Victoria Australia 37-48

Yvan Le Blanc (#1456) 860 Rood Pond Rd. Williamstown, VT 05679 38-66S

# Parts FOR SALE

| • 1937 & 1938 NOS PARTS FOR SALE  1937-40 Second speed gear. \$35 1937-40 Second and third speed sliding sleeve. \$25 1937 all, 1938-60-80-90 Crankshaft pilot bearing. \$10 1937-1938-40 NORS Clutch release equalizer ball stud bearings. \$3/pr 1937-1938 all, transmission main drive bearing. \$15 1937-1938 40-60 Outside door handle, non-locking, used (marked H30087 or H32253) \$10 ea 1937-1938 40-60 Outside door handle, non-locking, used (marked H17712 or H33912 or H30075) \$10 ea 1937 40 & 60 Locking door handle, less lock, 1st type with offset shank, #4074570, marked T195000 \$35 each 1938 40 & 60 Door handle, less lock, #4089306, marked T19541 \$35 1938 right taillamp door, used. \$10 1938 taillight lens, used. \$10 1938-40 After engine #4-3445305 rocker arm assembly, used. \$35 1037-1938 all generator armature. \$30 1937-1938 all generator armature. \$30 Parts are NOS except where noted. Please add 15% postage Bob Graves (#1136) 56 Dartmouth St. |
|---|
| • 1937 & 1938 NOS PARTS FOR SALE  1937-40 Second speed gear   |
| 1937-40 Second speed gear. \$35 1937-40 Second and third speed sliding sleeve. \$25 1937 all, 1938-60-80-90 Crankshaft pilot bearing. \$10 1937-1938-40 NORS Clutch release equalizer ball stud bearings \$3/pr 1937-1938 all, transmission main drive bearing \$15 1937-1938 40-60 Outside door handle, non-locking, used (marked H30087 or H32253) \$10 ea 1937-1938 40-60 Outside door handle, non-locking, used (marked H17712 or H33912 or H30075) \$10 ea 1937 40 & 60 Locking door handle, less lock, 1st type with offset shank, #4074570, marked T195000 \$35 each 1938 40 & 60 Door handle, less lock, #4089306, marked T19541 \$35 1938 right taillamp door, used. \$10 1938 taillight lens, used. \$10 1938-40 After engine #4-3445305 rocker arm assembly, used. \$35 1037-1938 40 starter armature. \$30 1937-1938 all generator armature. \$30 Parts are NOS except where noted. Please add 15% postage Bob Graves (#1136) 56 Dartmouth St.  |
| 1937-40 Second and third speed sliding sleeve   |
| 1937 all, 1938-60-80-90 Crankshaft pilot bearing  |
| 1937-1938-40 NORS Clutch release equalizer ball stud bearings   |
| 1937-1938 all, transmission main drive bearing  |
| 1937-1938 40-60 Outside door handle, non-locking, used (marked H30087 or H32253)  |
| used (marked H30087 or H32253)       \$10 ea         1937-1938 40-60 Outside door handle, non-locking,       \$10 ea         1937 40 & 60 Locking door handle, less lock,       \$15 each         1938 40 & 60 Door handle, less lock, #4089306, marked T195000       \$35 each         1938 right taillamp door, used.       \$10         1938 taillight lens, used.       \$10         1938-40 After engine #4-3445305 rocker arm assembly, used.       \$35         1037-1938 40 starter armature.       \$30         1937-1938 all generator armature.       \$30         Parts are NOS except where noted. Please add 15% postage       \$30         Bob Graves (#1136)       \$6 Dartmouth St.  |
| 1937-1938 40-60 Outside door handle, non-locking, used (marked H17712 or H33912 or H30075)  |
| used (marked H17712 or H33912 or H30075)  |
| 1937 40 & 60 Locking door handle, less lock,  1st type with offset shank, #4074570, marked T195000  |
| 1st type with offset shank, #4074570, marked T195000  |
| 1938 40 & 60 Door handle, less lock, #4089306, marked T19541. \$35 1938 right taillamp door, used. \$10 1938 taillight lens, used. \$10 1938-40 After engine #4-3445305 rocker arm assembly, used. \$35 1037-1938 40 starter armature. \$30 1937-1938 all generator armature. \$30 Parts are NOS except where noted. Please add 15% postage Bob Graves (#1136) 56 Dartmouth St.   |
| 1938 right taillamp door, used  |
| 1938 taillight lens, used   |
| 1938-40 After engine #4-3445305 rocker arm assembly, used   |
| 1037-1938 40 starter armature   |
| 1937-1938 all generator armature  |
| Parts are NOS except where noted. Please add 15% postage Bob Graves (#1136) 56 Dartmouth St.  |
| Bob Graves (#1136)<br>56 Dartmouth St.  |
|   |
| 4 7 4 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1   |
| Lynn, MA 01904  |
| (781) 593-9534 evenings   |
|   |
| • 1937 & 1938 PARTS FOR SALE  |
| <ul> <li>1937 Special Sidemount Fenders with the mounting hardware. No covers. Rough</li> </ul>   |
| condition. Were sandblasted and put in primer. These fenders could possibly be repaired,  |
| or used as patterns to convert plain to welled fenders\$400   |
| • 1938 Special Sidemount fenders with tire mounting hardware. No covers. One side   |
| has a 5" hole in the well. The other side is fine. Small tears in the wheel opening area  |
| but both easy to repair   |
| <ul> <li>6 Gallons of Ditzler Nitrocellouse Lacquer. 1937 color Sudan Blue.</li> </ul>  |
| 1938 color Botticelli Blue  |
| Mark Salamon (#1382)  |
| P.O. Box 397  |
| Bondsville, MA 01009  |
| Phone: (413) 283-3974. Leave message.   |

| p = 5 - 5 1   |  |
|---|--|
| Parts For Sale continued from page 26)  |  |
| • 1937 PARTS FOR SALE   | 124                                    |
| Big Series Sparkplug cover, nice original.                                    | \$90                                   |
| Hubcaps Fair-good condition, full set   | \$75                                   |
| Big Series Master cylinder parts & body, needs work                           | \$25                                   |
| Steve Nathanson (#656)  |  |
| Walnut Creek, CA.   |  |
| (925) 947-6711  |  |
|   |  |
| • 1937 & 1938 PARTS FOR SALE  |  |
| The following is just a portion of the parts available. Call with your needs. |  |
| 1937 PARTS FOR SALE   |  |
| 40/60 Series rear brake cables, good condition                                | \$40 pair                              |
| Master and deluxe heaters   | \$75 each                              |
| ROADMASTER rims   | \$25 each                              |
| ROADMASTER axles  |  |
| ROADMASTER front suspension   | call with needs                        |
| Coupe & 2 Dr. Sedan side stainless, complete sets                             | \$75                                   |
| CENTURY brake & clutch pedal assembly   |  |
| CENTURY radiator  |  |
| SPECIAL radiator  |  |
| Rear springs 40 & 60, good condition  |  |
| Radio delete plates   | \$15                                   |
|   |  |
| SMALL SERIES throttle linkage   |  |
| BIG SERIES rocker assemblies  |  |
| Fender lights   | 500 pair                               |
| Trunk lights, complete  | ٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠ |
| Tail lights with lenses, all series   |  |
| Wiper transmissions   | 550 pair                               |
| SPECIAL manifold  |  |
| Throttle cable  |  |
| SPECIAL transmission  |  |
| SPECIAL splash pans   | \$40 pair                              |
| CENTURY hood  | \$100                                  |
| Headlight switch  |  |
| Radio grilles   | \$15                                   |
| Wiper motors  | \$15                                   |
| Trunk hold-up arms  | \$20                                   |
| Sun visors  |  |
| Bumpers   |  |
| Bumper arms   |  |
| Steering wheel  |  |
| 40 & 60 running board brackets  |  |
| Buick creast badge for hood trim strip  |  |
| Gas pedal   |  |
| SMALL AND LARGE SERIES generators   |  |
| Radio   |  |
| LARGE SERIEs AA-2 carburetor, complete  |  |
| Instrument cluster with working temp. gauge                                   |  |
| • 1938 PARTS FOR SALE   |  |
| DeLuxe Heaters  | £75 and                                |
| Deluxe fleaters   |  |

| (Parts For Sale continued from page 27)              |            |
|--|------------|
| Trunk hold-up arms                                   | \$20       |
| 734Z starter with solenoid                           | \$50       |
| Horn button  |            |
| SPECIAL hood lettering                               |            |
| Defroster ducts                                      |            |
| Wiper transmissions                                  |            |
| Rear license plate stand, bracket & light for sedan  | \$45       |
| Tail lights, complete                                | \$75 pair  |
| Assist straps with screws                            | \$10 each  |
| Throttle cable                                       | 20         |
|  |            |
| SPECIAL radiator                                     |            |
| Battery tray   | 520        |
| Generator  | 550        |
| SPECIAL manifold, complete                           |            |
| SPECIAL hood sides & tops                            |            |
| Grille, no cracks, minor pitting                     |            |
| CENTURy radiator                                     | \$100      |
| SPECIAL coupe window moldings                        | \$100      |
| Cigarette lighter                                    | \$25       |
| Rear muffler hanger, NOS                             | \$35       |
| 4-Door sedan rear vent windows, excellent originals. | \$100 pr   |
| Trunk emblem   |            |
| Headlights, complete, originals                      |            |
|  | ээоо рг    |
| 1937 & 1938 PARTS FOR SALE                           | 63.5       |
| Radio hanger bracket                                 |            |
| BIG SERIES spark plug cover                          |            |
| SPECIAL running boards, solid cores                  |            |
| Headlight buckets                                    |            |
| LARGE SERIES air cleaner                             |            |
| 40-60 kingpin sets                                   |            |
| LARGE SERIES fan belts, new                          | \$15       |
| Map light switches                                   | \$15       |
| SMALL SERIES spark plug covers                       | \$40       |
| Rear fender splash aprons                            |            |
| BIG SERIES manifold ends                             | \$50       |
| 16" beauty rings                                     | \$10 each  |
| Headlight bezels                                     |            |
| Trunk hinges   |            |
|  |            |
| Front arm rests                                      | 525 pair   |
| 40 & 60 rear vent windows, need plating              |            |
| Rear view mirrors                                    |            |
| SPECIAL rear motor mounts                            |            |
| CENTURY rear motor mounts                            |            |
| 40 & 60 4 dr. sedan doors                            | \$50 each  |
| Front vent window frames & mechanisms                |            |
| BIG SERIES fuel pump cores                           |            |
| Keyed ignition switches                              |            |
| 4-Post voltage regulator, used                       | \$25       |
| 15" Beauty rings                                     |            |
| Handlight adjusting buckets                          | \$100 pair |
| Headlight adjusting buckets                          |            |
| Front license plate bracket                          |            |
| Horn ring, mint condition                            |            |
| Radio tuners   |            |
| Rear bumper gravel guards  Dave Tacheny (#997)       |            |
| 11949 Oregon Ave. N., Champlin, MN 55316             |            |
|  |            |

# Parts WANTED

#### WANTED:

For 1937 Special Convertible Coupe Model 46C

• Driver's side horn • Complete emergency brake cable & brackets

• Rumble seat lid drain spout for the right side

Lauren Matley (#46)

13912 SE 241st St., Kent, WA 98024

(253) 630-8887 (home)

# Gars FOR SALE

#### 1938 ROADMASTER FOR SALE:

 1938 Roadmaster Convertible Sedan Model 80C with sidemounts and covers

Needs complete restoration.

#### \$8,500.

 Also a 1940 Limited 80 Series Convertible Sedan Model 81C with sidemounts.
 Needs restoration.

#### \$22,000.

Red Praetorius Saugerties, NY (914) 246-9930

#### 1937 CENTURY FOR SALE:

1937 Century Model 61 4-Door Sedan. Very original, runs great, new www tires, 1937 California plates, nice original interior, fogs, dependable \$8.000.

Steve Nathanson (#656) Walnut Creek, CA. (925) 947-6711

#### 1938 SPECIAL FOR SALE:

1938 Special Model 47 4-Door Slant-back Sedan, Call for Q & A.

#### \$9,600.

Terry King (#826) (703) 237-0296 Washington DC Area





#### 1937 CENTURY FOR SALE:

Black 1937 Century 2-Door Trunk Back Sedan Model 68 Dual sidemounts, 61,500 miles (believed original), rust free, New LeBaron-Bonney interior, spotlight, radio, Deluxe heater-defroster, new wiring harness, 4 new Goodrich wide whitewalls, valves & manifold resurfaced, new fuel pump and carburetor, new motor and transmission mounts, new brakes, new wheel seals, new rubber throughout, excellent chrome. Car runs smooth and peppy.

A really neat car. Health forces sale.

#### \$19,500.

Howard Krieabel (#1415) 90 6th Ave., Collegeville, PA 19426 Phone: (610) 489-1253 E-mail: kriebel@erols.com

L man. artebere erois.com

## Back JAAues Still Available! THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 Volume X Numbers 1 through 9
  - 1992-1993 Volume XI Numbers 6 and 7
- 1993-1994 Volume XII Numbers 2, 4, and 6
- 1994-1995 Volume XIII Numbers 2, 4, and 6
- · 1995-1996 Volume XIV Numbers 3 through 6
- 1996-1997 Volume XV Numbers 4 through 6
- . 1997-1998 Volume XVI Numbers 1 through 6

Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA 

#### ONE OF A KIND CAR DISPLAY POSTERS!

Beautiful, Descriptive, Framed Collector Car

#### DISPLAY POSTERS

for Car Shows are my specialty. These Hand Made Posters really add that "SPECIAL TOUCH" when displayed next to your car. Prices start at \$50.00 and up depending on Color, Size and Rendering of your car. Al Lovi (#994)

ART DESIGN STUDIO 95 Brianne Circle, Windsor, CA 95492 (707) 837-1786

## CONVERTIBLE SUN VISORS





\$165.00 each

These are authentic visors. All parts are chrome plated.

#### WALLACE WAMSLEY

(619) 283-3063

4732 Bancroft Street #7, San Diego, California 92116

## 1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED. Complete Research Package \$50.00, \$60.00 if shipped outside the USA. Additional information available upon request, or send year, model, serial number, engine number, car photo (if available) and Fisher Body data plate rubbing.

#### 1937 BUICK HIGH QUALITY VIDEO

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.



UTOMOTIVE RESEARCH SERVICES



P.O. Box 4057, Apopka, Florida 32704-4057 • Phone 407-880-0797 • e-mail: BUICKOHV@aol.com.

FRONT FLOORMAT 1937-38 All Models Black or Brown FF-378.....\$195.



AUTOMOBILIA (805) 434-2963

### 1937-38 BUICK



| DOOR | WEATHERSEAL-SPONGE |
|------|--------------------|
|      |                    |

| Glue-in    | DW-378 | \$1.80 ft. |
|------------|--------|------------|
| Clip-in    | DW-80  | \$3.25 ft. |
| Clips      | WC-80  | \$ .75 ea. |
| DOOR BOTTO | M SEAL |            |
| Clip Type  | DW-369 | \$2.25 ft  |





| Ser. 80-9 | 90      | TW-371 | <br>\$35.50 |
|-----------|---------|--------|-------------|
| Sedans.   | 3/4° Wi | de;    |             |


| Ser | . 40-60 | TW-371S | · | \$37.5 | 0 |
|-----|---------|---------|---|--------|---|
|     |         |         |   |        |   |



| 1/2'x1'x16' TL-1129 | \$47 | 50 |
|---------------------|------|----|
|                     |      |    |







SHIFT BOOT, 1937-38 Series 40 Only!

Black ..... \$ 9.25 Brown.....\$18.50 Series 80-90 Black ONLY..... \$ 8.50

DOOR SILLS: Trim To Fit 2-Door \$62/pr. 4Door \$93/set. GLOVE BOXES; \$27, ea.

PARKING LIGHT LENS......\$18.00 ea

CARB. KITS:CARTER......CK-360C .\$27.00 STROMBERG...... CK-37XS .\$27.50

TORQUE BALL SEAL KIT. All Models TBK-343. ..... \$27.00

VISOR "VANITY" MIRROR, VM-379 ..... \$27. ea.

LICENSE PLATE FRAMES. Chromed Brass. LF-333P.....\$62. Pair

FRONT END PARTS For 40-60 Series; Upper Outer Kit......\$39.50 King Pin Sets......\$39.75 Lower Inner Bushings......\$20.00 Tie Rod End......\$27.00





EXHAUST MANIFOLDS 1937-38 Series 60-80-90 ENDS \$185. CENTER \$189. VALVE BODY \$195.

RUNNING BOARD INSULATORS, 1937-38 All Models, ALL NEW MATERIAL! 4 Needed Per Running Board.

RI-378S .... Set of 8 .. \$180.00

HOOD REST PADS. 1937-38 6-8 Per Car. 

DASH GLASS, SILK-SCREENED on Back of GLASS in COLORS as Original 1937 ..... SPEEDO DG-37 .... \$38. ......RADIO.....RG-37.....\$23. ......CLOCK .. CG-37 .... \$28. 1938...... SPEEDO DG-38 .... \$38. ......RADIO....RG-38.....\$23. ......CLOCK .. CG-38 .... \$28.

PLASTIC DASH KNOBS DK-37(38) ..... \$ 6. PLASTIC DOOR HANDLE and Window Winder RINGS . HE-37(38) ...... \$ 6.

OUTSIDE DOOR HANDLE CHROME and RUBBER GROMMETS. 1 FERRULE & 1 GROMMET Per Set. 1938 ..... DGF-380 ..... \$5./Set

DOOR FERRULE INSTALATION TOOL. \$20. Refundable if Returned Within 30 Days. DF-TOOL ......\$29.

1938 TRUNK HANDLE/LIGHT MOUNTING 

MOTOR MOUNT, FRONT, All Models ROUND PADS ...... SP-338 ... \$10. pr. MOUNT.......MM-347.. \$51. pr

TRUNK HINGES for 40-60. Chrome Plated \$150. pr.

1937 HUB CAPS, All Ser ..... HC-37 ..... \$60. ea. WHEEL Beauty Rings. 15" or 16" ...... \$99./Set of 4 1937 or 38 HOOD ORNAMENT...... \$85.

SOME OTHER ITEMS WE STOCK; BEARINGS. DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE. SHIPPING; 10%. max.\$9. min. \$4. Prepaid. C.O.D. Add \$5.

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #45 \$5.00 - PHONE ORDERS - (Write For Catalog)























## BUICK...Upholstery and Top Kits 1927/1955

Since 1977.. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete interior Kits Seat Upholstery, Tops and related accessories as well as "era" fabric by the yard...

Inquire Toll Free 1-888-388-8726



## HAMPTON

6 Chestnut St Tel 978-388-8047 Gach Am

Amesbury, MA Fax 978-388-1113



Restoration and repairs
that are correct
and authentic.
"I know your Buick."
Former Director of Long

Former Director of Long Island, NY Chapter now has fully equipped shop in North Georgia. Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945




## J.B. Donaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505



Thru 1953 Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



1927

1953

## WIRING HARNESSES

AUTHENTIC REPRODUCTION
WIRING SYSTEMS THRU 1953
HAND CRAFTED WITH THE
FINEST MATERIALS
EACH SUPPLIED WITH:
LIMITED WARRANTY
INSTALLATION INSTRUCTIONS
SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION \$5



BOX 435 WAYNE, PA. 19087

